

TECHNICAL DIVISION
SAVANNAH RIVER LABORATORY
MECHANICAL DEVELOPMENT GROUP

WSRC-RP-89-61

Keywords: DWPF,
RESEARCH MELTER,
MINI-MELTER

Derivative Classifier: Richard G. Waller

SRL
RECORD COPY

CC: C. W. Smith
J. R. Knight
H. F. Sturm
M. D. Boersma
C. T. Randall
L. F. Landon
J. T. Carter
M. J. Plodinec
P. M. Allen
D. N. Cowart
H. P. Gibson
GTG (9)
SRL Records (4)

April 14, 1989

TO: D. W. Wilkerson

FROM: D. L. Mensink *D.L.M.*

BUILDING 774A MINI-MELTER RESTORATION (U)

SUMMARY

Large scale mechanical improvements were made on the 100th scale glass melter in building 774A following a shutdown in November, 1988. The circumstances regarding that shutdown were reported by P. M. Allen in DPST-89-345. By request, the Mechanical Development Group assumed responsibility for the work on SRL Service order DS-87042. This report describes the changes which were made, their purpose, and observations as to their effectiveness after approximately 4 weeks of operating with the improvements in-place. Recommendations for further improving the equipment are also noted.

The old melter design, now superceded, is documented in drawings ST5-23838 through ST5-23847. As-built drawing arrangements and details for the new work is shown in drawings SK5-6191-LD through SK5-6197-LD. Other design details are referenced in the drawings which were developed for the new shielded cells Research Melter, ST5-25111 through ST5-25124.

RECORDS ADMINISTRATION



R1498708

Most of design concepts used to modify the Mini-Melter were replicated from the new Research Melter, a Mechanical Development Group project that was commissioned earlier on SRL service order DS-87028. These improvements were possible, mostly in part, due to available spare parts and documented design for the new generation Research Melter.

This work represents over 80 man-days of Mechanical Development effort (Project Assistant effort included) committed to the DWPF research program within the period from December 1988 to February 1989. Clearly, this obligation to DWPF was essential in meeting their desired target time period of 8 weeks from initial review. In spite of the holiday season, the work was completed within one week of projection. Exceptional support from the SRL shops and the use of Computer Aided Design tools were essential factors.

DESIGN MODIFICATIONS

Reduced air in-leakage

The problem of excessive air in-leakage in the melter has been well documented. The primary source was the pour chamber and door. Air was drawn directly in around the door, through the pour chamber and into the plenum. Air could also be drawn into the plenum through leaks around the penetrations for each of 3 Silicon Carbide bayonet heaters used to heat the Pour Chamber.

Air in-leakage through the pour chamber is blocked by isolating the pour chamber within a 1/8" thick stainless steel box. The box measures 12" wide x 18" high x 8" deep. Edges around the open side in front of the box are seal welded where they intersect with the lower half of the melter shell. Leaks between the box and the insulation filled lid are restricted by close fits (see reference SK5-6191-LD, front view of melter). Slack sections between those surfaces are packed with Kaowool bulk fiber wool and paper products. A seal is established in the space above the top of the box with two rows of compressed packing constructed by loose rolling 1/8" Kaowool 2300 paper into 3/4" Dia. x 1/4" wall tubular lengths.

A secondary source of air in-leakage existed at the opening for the bayonet lid heaters. There was an approximately 4" high x 10" long rectangular opening in the side shell of the lid. This opening exposed the ends of (2) 1.5" Dia. mullite refractory sleeves loosely fit into holes through insulation in the lid. 3/4" Dia. silicon carbide bayonet lid heaters rested loosely in these sleeves. The ends of the sleeves tubes and openings in the insulation provided in-leakage direct to the plenum. This is corrected by redesign of the lid heaters.

Recommendation:

Because the melter system presently has no means for determining vacuum levels in the plenum, there is no adequate method to evaluate the magnitude or acceptability of in-leakage levels. In light of our desire to emulate DWPF air to glass ratios, the future addition of a vacuum measuring device for the plenum is recommended in order to properly assess leak rates and establish design direction. The unused sampling port in the lid would be a good location for installing a manometer.

Improved Lid Heater Design

The lid heaters were redesigned in the same fashion as the new Research Melter, including an improved mounting method (see reference ST5-25114). A 3/4" Dia. silicon carbide bayonet heater is inserted into a protective McDaniel mullite tubular sleeve and the terminal end is cast into a stainless steel housing with Sauerlesen No. 31 Cement. This forms a modular cartridge which is then gasketed and bolted, air tight, to the melter shell. Housings are constructed of a gasket seating flange ring welded to a short length of corrugated stainless steel hose. The hose corrugations keep the terminals cool. The heaters were purchased with longer active heating lengths (corresponding with an enlarged plenum space) for improved start-up heating.

Each lid heater is now supported concentrically within its protective sleeve by stacks of Kaowool paper rings located at inactive regions at the ends. This attenuates an undesirable condition in which the heaters rested in contact with the bottom of their protective sleeves. This point was brought to our attention by Carborundum, the manufacturer of the heating elements. Reduced heater life and premature failures were cited.

Improved glass pouring and pour chamber heating

The shutdown of the Mini-Melter was attributed in a large part to problems in pouring. Other similar problems in the past have resulted in many aborted runs. The correction of these problems was a primary objective in the design of the new Research Melter. Many of those design solutions for improved glass pouring in the Research Melter were incorporated into the rebuild of the Mini-Melter.

The inside diameter of the pour spout, through which glass flows, has been enlarged from 1/2" to over 0.8". A slot for venting has also been placed over top of the exiting leg section of the spout in order to prevent possible vapor lock in the bend.

Recommendation:

A similar slot should be added to the Research Melter. Vapor lock in the neck was not considered at the time that design was developed.

Heat losses to the Pour Chamber have been reduced greatly. Direct chimney losses into the plenum were eliminated by isolating the pour chamber as discussed earlier. The pour chamber has been shortened flush to the front of the melter so as to reduce convective losses at the exposed sides of the extension. This measure also reduces the amount of pour chamber volume to be heated.

Three 1/2" Dia. x 6" long silicon carbide bayonet heaters were used to heat the pour chamber. They were fragile and often broke during installation. Cantilever supported at the front of the melter, they were constantly stressed by their own dead weight and subject to mechanical abuse from canister handling operations as well as normal movements and vibrations of the melter structure. Their maximum combined heat output was 750 watts @ 117 VAC max. input. The 117 VAC max. input rating caused difficulties in balancing the 3 phase transformer which services the melter, a practice essential to efficient transformer operation.

Two highly durable semi-circular ceramic plate heaters were installed in the pour chamber. Total heating capacity is now 1500 watts. Their input voltage is 220 VAC which matches the lid heaters. This match simplifies load balancing on the transformer. In advantage of their semi-circular shape, we have oriented them in manner that the pour spout, the most critical surface, occurs at the focal point of heating. In short, we now deliver 100% more heat to 50% less pour chamber volume with far fewer heat losses in order to facilitate improved pouring.

Upper Shell (Lid) Repairs

Restoration of the Mini-Melter included complete removal of all internals from the shell including insulation. Upon examination of the empty shell we discovered severe stress corrosion cracking in the top of lid. This conclusion was confirmed by D. Bickford. Repairs were made consisting of a 1/8" stainless steel plate patch (see figure 1) welded to the inside of the lid.

Plenum Residence Time

As in the Research Melter the plenum volume is enlarged slightly to match the DWPF melter residence time. This is an important factor in off-gas characterization studies.

Improved Plenum Heating

Two lid heaters, located in the plenum, supplied heat necessary for start-up. During operation they provide trim heating to stabilize the melting process and they maintain the melt during electrode outages. Before, the net available amount of heat was insufficient to assure smooth start-up of the unit.

The heaters were replaced with a new design outlined earlier in this report. Additionally, (2) extra heaters were installed from

the opposite side of the lid. The Mini-Melter now has a total of (4) lid.

The heating improvements, combined with air in-leakage reductions, are credited for the "effortless" start-up of the Mini-Melter this March.

Improved Tilt Mechanism

The current melters are tilted to pour. The present design of the tilting mechanism is inadequate. Premature failure of air actuating cylinders and jerking action during tilt have been cited. An improved tilting mechanism for the melters has been developed by D. N. Cowart in the LSD Mechanical Development Group. Dave plans to present his solution separately in another report.

Spill Protection

The old Mini-Melter had no means for containing glass in the event of melt chamber overflow. Correspondingly, there was no provision to avoid breach of electrical isolation between Melt potential and the outer shell of the melter.

A containment weir has been installed in the forward half of the secondary container. This weir will provide partial spill containment up to an estimated 15% of the melt volume. Although unlikely, overflows exceeding this margin will then be diverted away from structures which are connected to the shell.

This is not a problem in the new Research Melter.

Recommendation:

Development of a glass level indicating device in the melt chamber is recommended. This is consistent with strategies for avoiding overflow conditions and reducing demands for surveillance. Similarly, a device or system for indication of a full level in canisters should be investigated and then integrated into a reliable response system.

COMPARISON OF DESIGN - RESEARCH MELTER vs MINI-MELTER

In light of feature similarities between new Research Melter and restored mini-melter, a comparison of differences follows to place future melter performance evaluations in correct perspective. Because the new design holds several outstanding advantages, a continued program to replace the Mini-Melter is still recommended.

Both melters address the need for higher peak heating in the plenum. However, they differ in approach. The Mini-Melter has two extra heaters whereas the Research Melter is equipped with an Inconel 690 plate ceiling in the cover assembly. I anticipate significant amount of heat reflection will occur back into the plenum as a result of this ceiling.

The Research Melter is believed to be more air tight. The lid is seated in a more reliable manner. Although improved, the Mini-Melter envelope is compromised somewhat by a difficult seam between the lid and the upper portion of the pour chamber. This is avoided in the Research Melter by relocating the lid flange and casting the pour chamber into a separate shell. This new technique should enhance leak tightness between plenum and pour chamber.

Feed entrainment in the off-gas flow should be less of a problem in the new Research Melter. Here the off-gas nozzle is moved 2" further away from the feeding inlet. This may be important for demonstrating new feed atomization techniques in the melters.

The Research Melter pour spout has a bubble pump to assist pouring. The Mini-Melter does not.

Viewing the melt surface should be easier in the new Research Melter. The old sample port location is superseded with an additional sight viewing port. Both sight ports have larger diameters and are shortened to increase the view angle.

Door Modifications

A tightly gasketed door has been provided, an improvement which may enable the future development of differential pressure unloading. The door has been equipped with a sight glass for viewing the pour stream. Previously, no sight glass in the door existed. Operators were required to open the door in able to check canister levels and pouring status. Consequently, the new arrangement will conserve valuable plenum heat.

The door makes up to a stiff frame constructed of 1 5/8" stainless steel unistrut. Four quick make-up Destaco type clamps provide up to 600 lbf each for seating the door tightly closed. A special hinged davit has been provided for smooth door operations. When opened, the door can be quickly swung out of the working area, a very desirable feature for canister handling.

The door unexpectedly warped upon start-up of the Mini-Melter. This problem is typical of residually stressed 304 stainless steel plate products. I have presented, to P. M. Allen, a correction which involves the addition of stiffening structures. Logically, this recommendation should be implemented on both melters.

MISCELLANEOUS IMPROVEMENTS

Special sealing and insulating electrical feed-thru fittings were purchased from the Conax Corp. to assure leak-proof electrical connections to the new pour chamber heaters. The feed-thru's are constructed of 1/4" Dia. Nickel rods threaded at each end for 1/4-20 nickel jam nuts. Nickel provides good conductivity at the high pour chamber temperatures and good corrosion resistance. The

nickel parts were purchased from Standard Nut and Bolt in Cumberland, NY. I found them to be very economical.

Two additional feed-thru ports were provided in the door frame as spare ports for future use.

New Inconel 690 Electrodes were fabricated in the SRL shops as part of the work. As with the new Research Melter, their design is essentially duplicated from earlier documentation. During inspection of the welded assemblies it was found that joints in the 3/8" X 1/2" bus bars were not full penetration welded. They were butted without beveling and the seams were fused in manner which produced only partial penetration. Uncorrect, their current carrying capacity would have been severely limited. The deficiency is now corrected.

Five holes were drilled in the K-3 casting in the bottom of the Melt chamber and 5/8" OD x 1/4" ID x 1/2" deep ceramic wells were installed into those holes in conjunction with requirements of the noble metals campaign.

The Mini-Melter was restarted under power from a new electrical power supply. This is discussed elsewhere.

Special precautions were observed in handling of the Kaowool Refractory Ceramic Fiber (RCF) insulation. The procedures paralleled those required for asbestos handling.

Recommendation:

Investigation of suitable replacement insulating materials is recommended due to the high degree of health protection precautions mandated by the use of RCFs. Future DWPF programs will continue to demand the use of high performance insulation forms. Industry developments as well site policies concerning the health status of these materials should be closely monitored.


As illustrated by the door, this work has granted us an opportunity for evaluating new design changes pertinent to the Research Melter before it is commissioned to the Shielded Cells.


ACKNOWLEDGEMENTS

The success and timeliness of the work was due in large part to excellent support from the Melter Task Team. Special recognition is also warranted for the following individuals for their contributions which were absolutely essential for meeting this objective: Don Diamond and George Hammack for melter construction and help in project coordination; Ron Blessing for documenting the work and aiding in construction; David Healy for help with the insulation; and Mike Stowell, Jerry Okeson, Jeff Cunningham, Bobby

Bryant and the SRL shops for the timeliness and quality of part fabrication.

FIGURE 1
MINI-MELTER RESTORATION
PATCH PLATE FOR LID





VIEW F - F
(DOOR REMOVED FOR CLARITY)


VIEW D - D

ITEM	QUAN	PART/DRWG	DESCRIPTION	MAT'L
1	1	COVER PLATE	ALUMINUM	ALUMINUM
2	1	DOOR	ALUMINUM	ALUMINUM
3	1	DOOR LATCH	STEEL	STEEL
4	1	DOOR LATCH	STEEL	STEEL
5	1	DOOR LATCH	STEEL	STEEL
6	1	DOOR LATCH	STEEL	STEEL
7	1	DOOR LATCH	STEEL	STEEL
8	1	DOOR LATCH	STEEL	STEEL
9	1	DOOR LATCH	STEEL	STEEL
10	1	DOOR LATCH	STEEL	STEEL
11	1	DOOR LATCH	STEEL	STEEL
12	1	DOOR LATCH	STEEL	STEEL
13	1	DOOR LATCH	STEEL	STEEL
14	1	DOOR LATCH	STEEL	STEEL
15	1	DOOR LATCH	STEEL	STEEL
16	1	DOOR LATCH	STEEL	STEEL
17	1	DOOR LATCH	STEEL	STEEL
18	1	DOOR LATCH	STEEL	STEEL
19	1	DOOR LATCH	STEEL	STEEL
20	1	DOOR LATCH	STEEL	STEEL
21	1	DOOR LATCH	STEEL	STEEL
22	1	DOOR LATCH	STEEL	STEEL
23	1	DOOR LATCH	STEEL	STEEL
24	1	DOOR LATCH	STEEL	STEEL
25	1	DOOR LATCH	STEEL	STEEL


SK-6281-LD

MINI-MELTER
REPAIRS & MODIFICATIONS
FRONT VIEWS
VIEW F - F

UNITED STATES GOVERNMENT
L. L. DUBOIS RESEARCH & CON. INC.
SAVANNAH, GEORGIA 31406



SECTION B-B



SECTION A-A


ITEM QUAN	PART/DESC	DESCRIPTION	MATL
1	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
2	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
3	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
4	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
5	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
6	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
7	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
8	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
9	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
10	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
11	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
12	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
13	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
14	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
15	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
16	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
17	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
18	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
19	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
20	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
21	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307
22	1/2" DIA. STEEL ROD	1/2" DIA. STEEL ROD	SAE 307

SAE 8292-LD
 REPAIR MODIFICATIONS
 SECTIONS A-A & B-B
 MINI-METTER
 E. J. DU PONT DE NEMOURS & CO., INC.
 SAVANNAH, MISSISSIPPI

NOTES:
 1. ALL DIMENSIONS ARE IN INCHES.
 2. ALL DIMENSIONS ARE TO CENTER UNLESS OTHERWISE SPECIFIED.
 3. ALL DIMENSIONS ARE TO BE MAINTAINED.
 4. ALL DIMENSIONS ARE TO BE MAINTAINED.
 5. ALL DIMENSIONS ARE TO BE MAINTAINED.
 6. ALL DIMENSIONS ARE TO BE MAINTAINED.
 7. ALL DIMENSIONS ARE TO BE MAINTAINED.
 8. ALL DIMENSIONS ARE TO BE MAINTAINED.
 9. ALL DIMENSIONS ARE TO BE MAINTAINED.
 10. ALL DIMENSIONS ARE TO BE MAINTAINED.
 11. ALL DIMENSIONS ARE TO BE MAINTAINED.
 12. ALL DIMENSIONS ARE TO BE MAINTAINED.
 13. ALL DIMENSIONS ARE TO BE MAINTAINED.
 14. ALL DIMENSIONS ARE TO BE MAINTAINED.
 15. ALL DIMENSIONS ARE TO BE MAINTAINED.
 16. ALL DIMENSIONS ARE TO BE MAINTAINED.
 17. ALL DIMENSIONS ARE TO BE MAINTAINED.
 18. ALL DIMENSIONS ARE TO BE MAINTAINED.
 19. ALL DIMENSIONS ARE TO BE MAINTAINED.
 20. ALL DIMENSIONS ARE TO BE MAINTAINED.
 21. ALL DIMENSIONS ARE TO BE MAINTAINED.
 22. ALL DIMENSIONS ARE TO BE MAINTAINED.

LATEST REVISION
 10/1/89

ITEM QUAN	PART/DRWG	DESCRIPTION	WALT
1	10	REPAIR SIDE VIEW	10
2	11	REPAIR SIDE VIEW	11
3	12	REPAIR SIDE VIEW	12
4	13	REPAIR SIDE VIEW	13
5	14	REPAIR SIDE VIEW	14
6	15	REPAIR SIDE VIEW	15
7	16	REPAIR SIDE VIEW	16
8	17	REPAIR SIDE VIEW	17
9	18	REPAIR SIDE VIEW	18
10	19	REPAIR SIDE VIEW	19
11	20	REPAIR SIDE VIEW	20
12	21	REPAIR SIDE VIEW	21
13	22	REPAIR SIDE VIEW	22
14	23	REPAIR SIDE VIEW	23
15	24	REPAIR SIDE VIEW	24
16	25	REPAIR SIDE VIEW	25
17	26	REPAIR SIDE VIEW	26
18	27	REPAIR SIDE VIEW	27
19	28	REPAIR SIDE VIEW	28
20	29	REPAIR SIDE VIEW	29
21	30	REPAIR SIDE VIEW	30
22	31	REPAIR SIDE VIEW	31
23	32	REPAIR SIDE VIEW	32
24	33	REPAIR SIDE VIEW	33
25	34	REPAIR SIDE VIEW	34
26	35	REPAIR SIDE VIEW	35
27	36	REPAIR SIDE VIEW	36
28	37	REPAIR SIDE VIEW	37
29	38	REPAIR SIDE VIEW	38
30	39	REPAIR SIDE VIEW	39
31	40	REPAIR SIDE VIEW	40
32	41	REPAIR SIDE VIEW	41
33	42	REPAIR SIDE VIEW	42
34	43	REPAIR SIDE VIEW	43
35	44	REPAIR SIDE VIEW	44
36	45	REPAIR SIDE VIEW	45
37	46	REPAIR SIDE VIEW	46
38	47	REPAIR SIDE VIEW	47
39	48	REPAIR SIDE VIEW	48
40	49	REPAIR SIDE VIEW	49
41	50	REPAIR SIDE VIEW	50
42	51	REPAIR SIDE VIEW	51
43	52	REPAIR SIDE VIEW	52
44	53	REPAIR SIDE VIEW	53
45	54	REPAIR SIDE VIEW	54
46	55	REPAIR SIDE VIEW	55
47	56	REPAIR SIDE VIEW	56
48	57	REPAIR SIDE VIEW	57
49	58	REPAIR SIDE VIEW	58
50	59	REPAIR SIDE VIEW	59
51	60	REPAIR SIDE VIEW	60
52	61	REPAIR SIDE VIEW	61
53	62	REPAIR SIDE VIEW	62
54	63	REPAIR SIDE VIEW	63
55	64	REPAIR SIDE VIEW	64
56	65	REPAIR SIDE VIEW	65
57	66	REPAIR SIDE VIEW	66
58	67	REPAIR SIDE VIEW	67
59	68	REPAIR SIDE VIEW	68
60	69	REPAIR SIDE VIEW	69
61	70	REPAIR SIDE VIEW	70
62	71	REPAIR SIDE VIEW	71
63	72	REPAIR SIDE VIEW	72
64	73	REPAIR SIDE VIEW	73
65	74	REPAIR SIDE VIEW	74
66	75	REPAIR SIDE VIEW	75
67	76	REPAIR SIDE VIEW	76
68	77	REPAIR SIDE VIEW	77
69	78	REPAIR SIDE VIEW	78
70	79	REPAIR SIDE VIEW	79
71	80	REPAIR SIDE VIEW	80
72	81	REPAIR SIDE VIEW	81
73	82	REPAIR SIDE VIEW	82
74	83	REPAIR SIDE VIEW	83
75	84	REPAIR SIDE VIEW	84
76	85	REPAIR SIDE VIEW	85
77	86	REPAIR SIDE VIEW	86
78	87	REPAIR SIDE VIEW	87
79	88	REPAIR SIDE VIEW	88
80	89	REPAIR SIDE VIEW	89
81	90	REPAIR SIDE VIEW	90
82	91	REPAIR SIDE VIEW	91
83	92	REPAIR SIDE VIEW	92
84	93	REPAIR SIDE VIEW	93
85	94	REPAIR SIDE VIEW	94
86	95	REPAIR SIDE VIEW	95
87	96	REPAIR SIDE VIEW	96
88	97	REPAIR SIDE VIEW	97
89	98	REPAIR SIDE VIEW	98
90	99	REPAIR SIDE VIEW	99
91	100	REPAIR SIDE VIEW	100



LEFT SIDE VIEW

20.5-8201-10


REPAIR SIDE VIEW

REPAIR SIDE VIEW

REPAIR SIDE VIEW


ITEM	QUAN	PART/DRWG	DESCRIPTION	WALT
1	10	REPAIR SIDE VIEW	REPAIR SIDE VIEW	10
2	11	REPAIR SIDE VIEW	REPAIR SIDE VIEW	11
3	12	REPAIR SIDE VIEW	REPAIR SIDE VIEW	12
4	13	REPAIR SIDE VIEW	REPAIR SIDE VIEW	13
5	14	REPAIR SIDE VIEW	REPAIR SIDE VIEW	14
6	15	REPAIR SIDE VIEW	REPAIR SIDE VIEW	15
7	16	REPAIR SIDE VIEW	REPAIR SIDE VIEW	16
8	17	REPAIR SIDE VIEW	REPAIR SIDE VIEW	17
9	18	REPAIR SIDE VIEW	REPAIR SIDE VIEW	18
10	19	REPAIR SIDE VIEW	REPAIR SIDE VIEW	19
11	20	REPAIR SIDE VIEW	REPAIR SIDE VIEW	20
12	21	REPAIR SIDE VIEW	REPAIR SIDE VIEW	21
13	22	REPAIR SIDE VIEW	REPAIR SIDE VIEW	22
14	23	REPAIR SIDE VIEW	REPAIR SIDE VIEW	23
15	24	REPAIR SIDE VIEW	REPAIR SIDE VIEW	24
16	25	REPAIR SIDE VIEW	REPAIR SIDE VIEW	25
17	26	REPAIR SIDE VIEW	REPAIR SIDE VIEW	26
18	27	REPAIR SIDE VIEW	REPAIR SIDE VIEW	27
19	28	REPAIR SIDE VIEW	REPAIR SIDE VIEW	28
20	29	REPAIR SIDE VIEW	REPAIR SIDE VIEW	29
21	30	REPAIR SIDE VIEW	REPAIR SIDE VIEW	30
22	31	REPAIR SIDE VIEW	REPAIR SIDE VIEW	31
23	32	REPAIR SIDE VIEW	REPAIR SIDE VIEW	32
24	33	REPAIR SIDE VIEW	REPAIR SIDE VIEW	33
25	34	REPAIR SIDE VIEW	REPAIR SIDE VIEW	34
26	35	REPAIR SIDE VIEW	REPAIR SIDE VIEW	35
27	36	REPAIR SIDE VIEW	REPAIR SIDE VIEW	36
28	37	REPAIR SIDE VIEW	REPAIR SIDE VIEW	37
29	38	REPAIR SIDE VIEW	REPAIR SIDE VIEW	38
30	39	REPAIR SIDE VIEW	REPAIR SIDE VIEW	39
31	40	REPAIR SIDE VIEW	REPAIR SIDE VIEW	40
32	41	REPAIR SIDE VIEW	REPAIR SIDE VIEW	41
33	42	REPAIR SIDE VIEW	REPAIR SIDE VIEW	42
34	43	REPAIR SIDE VIEW	REPAIR SIDE VIEW	43
35	44	REPAIR SIDE VIEW	REPAIR SIDE VIEW	44
36	45	REPAIR SIDE VIEW	REPAIR SIDE VIEW	45
37	46	REPAIR SIDE VIEW	REPAIR SIDE VIEW	46
38	47	REPAIR SIDE VIEW	REPAIR SIDE VIEW	47
39	48	REPAIR SIDE VIEW	REPAIR SIDE VIEW	48
40	49	REPAIR SIDE VIEW	REPAIR SIDE VIEW	49
41	50	REPAIR SIDE VIEW	REPAIR SIDE VIEW	50
42	51	REPAIR SIDE VIEW	REPAIR SIDE VIEW	51
43	52	REPAIR SIDE VIEW	REPAIR SIDE VIEW	52
44	53	REPAIR SIDE VIEW	REPAIR SIDE VIEW	53
45	54	REPAIR SIDE VIEW	REPAIR SIDE VIEW	54
46	55	REPAIR SIDE VIEW	REPAIR SIDE VIEW	55
47	56	REPAIR SIDE VIEW	REPAIR SIDE VIEW	56
48	57	REPAIR SIDE VIEW	REPAIR SIDE VIEW	57
49	58	REPAIR SIDE VIEW	REPAIR SIDE VIEW	58
50	59	REPAIR SIDE VIEW	REPAIR SIDE VIEW	59
51	60	REPAIR SIDE VIEW	REPAIR SIDE VIEW	60
52	61	REPAIR SIDE VIEW	REPAIR SIDE VIEW	61
53	62	REPAIR SIDE VIEW	REPAIR SIDE VIEW	62
54	63	REPAIR SIDE VIEW	REPAIR SIDE VIEW	63
55	64	REPAIR SIDE VIEW	REPAIR SIDE VIEW	64
56	65	REPAIR SIDE VIEW	REPAIR SIDE VIEW	65
57	66	REPAIR SIDE VIEW	REPAIR SIDE VIEW	66
58	67	REPAIR SIDE VIEW	REPAIR SIDE VIEW	67
59	68	REPAIR SIDE VIEW	REPAIR SIDE VIEW	68
60	69	REPAIR SIDE VIEW	REPAIR SIDE VIEW	69
61	70	REPAIR SIDE VIEW	REPAIR SIDE VIEW	70
62	71	REPAIR SIDE VIEW	REPAIR SIDE VIEW	71
63	72	REPAIR SIDE VIEW	REPAIR SIDE VIEW	72
64	73	REPAIR SIDE VIEW	REPAIR SIDE VIEW	73
65	74	REPAIR SIDE VIEW	REPAIR SIDE VIEW	74
66	75	REPAIR SIDE VIEW	REPAIR SIDE VIEW	75
67	76	REPAIR SIDE VIEW	REPAIR SIDE VIEW	76
68	77	REPAIR SIDE VIEW	REPAIR SIDE VIEW	77
69	78	REPAIR SIDE VIEW	REPAIR SIDE VIEW	78
70	79	REPAIR SIDE VIEW	REPAIR SIDE VIEW	79
71	80	REPAIR SIDE VIEW	REPAIR SIDE VIEW	80
72	81	REPAIR SIDE VIEW	REPAIR SIDE VIEW	81
73	82	REPAIR SIDE VIEW	REPAIR SIDE VIEW	82
74	83	REPAIR SIDE VIEW	REPAIR SIDE VIEW	83
75	84	REPAIR SIDE VIEW	REPAIR SIDE VIEW	84
76	85	REPAIR SIDE VIEW	REPAIR SIDE VIEW	85
77	86	REPAIR SIDE VIEW	REPAIR SIDE VIEW	86
78	87	REPAIR SIDE VIEW	REPAIR SIDE VIEW	87
79	88	REPAIR SIDE VIEW	REPAIR SIDE VIEW	88
80	89	REPAIR SIDE VIEW	REPAIR SIDE VIEW	89
81	90	REPAIR SIDE VIEW	REPAIR SIDE VIEW	90
82	91	REPAIR SIDE VIEW	REPAIR SIDE VIEW	91
83	92	REPAIR SIDE VIEW	REPAIR SIDE VIEW	92
84	93	REPAIR SIDE VIEW	REPAIR SIDE VIEW	93
85	94	REPAIR SIDE VIEW	REPAIR SIDE VIEW	94
86	95	REPAIR SIDE VIEW	REPAIR SIDE VIEW	95
87	96	REPAIR SIDE VIEW	REPAIR SIDE VIEW	96
88	97	REPAIR SIDE VIEW	REPAIR SIDE VIEW	97
89	98	REPAIR SIDE VIEW	REPAIR SIDE VIEW	98
90	99	REPAIR SIDE VIEW	REPAIR SIDE VIEW	99
91	100	REPAIR SIDE VIEW	REPAIR SIDE VIEW	100

VIEW D-D
(LID REMOVED)



ITEM	QTY	PART/DESC	DESCRIPTION	MAT'L
1	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
2	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
3	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
4	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
5	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
6	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
7	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
8	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
9	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
10	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
11	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
12	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS
13	1	1/2" DIA. 304-SS. 1/2" THICK	1/2" DIA. 304-SS. 1/2" THICK	304-SS

VIEW C-C









304-SS. 1/2" DIA.

REPAIR MODIFICATIONS
VIEWS D-D & C-C

MINI-MELTER
REPAIR MODIFICATIONS
VIEWS D-D & C-C

LA 1151 REV. 10/89
ON THE DRAWING

[illegible]

POWER CHAMBER
(1) REQ'D

I

HINGE MOUNT
(2) REQ'D

CLAMP MOUNT
(4) REQ'D






SK5-6295-1D

THE

UNITED STATES DEPARTMENT OF ENERGY	
E. L. DU PONT DE NEMOURS & CO., INC.	
SAVANNAH RIVER PLANT	

MAN-WEILER
REPAIR WORKSHOPS
PSC. NEW PARTS AND DETAILS

**LATEST REVISION
ON THIS DRAWING**



ITEM	QUANTITY	DESCRIPTION	DATE	PRICE	TOTAL
1	1	1000 GAL	1/18/04	5.00	5.00
2	1	1000 GAL	1/18/04	5.00	5.00
3	1	1000 GAL	1/18/04	5.00	5.00
4	1	1000 GAL	1/18/04	5.00	5.00
5	1	1000 GAL	1/18/04	5.00	5.00
6	1	1000 GAL	1/18/04	5.00	5.00
7	1	1000 GAL	1/18/04	5.00	5.00
8	1	1000 GAL	1/18/04	5.00	5.00
9	1	1000 GAL	1/18/04	5.00	5.00
10	1	1000 GAL	1/18/04	5.00	5.00
11	1	1000 GAL	1/18/04	5.00	5.00
12	1	1000 GAL	1/18/04	5.00	5.00
13	1	1000 GAL	1/18/04	5.00	5.00
14	1	1000 GAL	1/18/04	5.00	5.00
15	1	1000 GAL	1/18/04	5.00	5.00
16	1	1000 GAL	1/18/04	5.00	5.00
17	1	1000 GAL	1/18/04	5.00	5.00
18	1	1000 GAL	1/18/04	5.00	5.00
19	1	1000 GAL	1/18/04	5.00	5.00
20	1	1000 GAL	1/18/04	5.00	5.00
21	1	1000 GAL	1/18/04	5.00	5.00
22	1	1000 GAL	1/18/04	5.00	5.00
23	1	1000 GAL	1/18/04	5.00	5.00
24	1	1000 GAL	1/18/04	5.00	5.00
25	1	1000 GAL	1/18/04	5.00	5.00
26	1	1000 GAL	1/18/04	5.00	5.00
27	1	1000 GAL	1/18/04	5.00	5.00
28	1	1000 GAL	1/18/04	5.00	5.00
29	1	1000 GAL	1/18/04	5.00	5.00
30	1	1000 GAL	1/18/04	5.00	5.00
31	1	1000 GAL	1/18/04	5.00	5.00
32	1	1000 GAL	1/18/04	5.00	5.00
33	1	1000 GAL	1/18/04	5.00	5.00
34	1	1000 GAL	1/18/04	5.00	5.00
35	1	1000 GAL	1/18/04	5.00	5.00
36	1	1000 GAL	1/18/04	5.00	5.00
37	1	1000 GAL	1/18/04	5.00	5.00
38	1	1000 GAL	1/18/04	5.00	5.00
39	1	1000 GAL	1/18/04	5.00	5.00
40	1	1000 GAL	1/18/04	5.00	5.00
41	1	1000 GAL	1/18/04	5.00	5.00
42	1	1000 GAL	1/18/04	5.00	5.00
43	1	1000 GAL	1/18/04	5.00	5.00
44	1	1000 GAL	1/18/04	5.00	5.00
45	1	1000 GAL	1/18/04	5.00	5.00
46	1	1000 GAL	1/18/04	5.00	5.00
47	1	1000 GAL	1/18/04	5.00	5.00
48	1	1000 GAL	1/18/04	5.00	5.00
49	1	1000 GAL	1/18/04	5.00	5.00
50	1	1000 GAL	1/18/04	5.00	5.00
51	1	1000 GAL	1/18/04	5.00	5.00
52	1	1000 GAL	1/18/04	5.00	5.00
53	1	1000 GAL	1/18/04	5.00	5.00
54	1	1000 GAL	1/18/04	5.00	5.00
55	1	1000 GAL	1/18/04	5.00	5.00
56	1	1000 GAL	1/18/04	5.00	5.00
57	1	1000 GAL	1/18/04	5.00	5.00
58	1	1000 GAL	1/18/04	5.00	5.00
59	1	1000 GAL	1/18/04	5.00	5.00
60	1	1000 GAL	1/18/04	5.00	5.00
61	1	1000 GAL	1/18/04	5.00	5.00
62	1	1000 GAL	1/18/04	5.00	5.00
63	1	1000 GAL	1/18/04	5.00	5.00
64	1	1000 GAL	1/18/04	5.00	5.00
65	1	1000 GAL	1/18/04	5.00	5.00
66	1	1000 GAL	1/18/04	5.00	5.00
67	1	1000 GAL	1/18/04	5.00	5.00
68	1	1000 GAL	1/18/04	5.00	5.00
69	1	1000 GAL	1/18/04	5.00	5.00
70	1	1000 GAL	1/18/04	5.00	5.00
71	1	1000 GAL	1/18/04	5.00	5.00
72	1	1000 GAL	1/18/04	5.00	5.00
73	1	1000 GAL	1/18/04	5.00	5.00
74	1	1000 GAL	1/18/04	5.00	5.00
75	1	1000 GAL	1/18/04	5.00	5.00
76	1	1000 GAL	1/18/04	5.00	5.00
77	1	1000 GAL	1/18/04	5.00	5.00
78	1	1000 GAL	1/18/04	5.00	5.00
79	1	1000 GAL	1/18/04	5.00	5.00
80	1	1000 GAL	1/18/04	5.00	5.00
81	1	1000 GAL	1/18/04	5.00	5.00
82	1	1000 GAL	1/18/04	5.00	5.00
83	1	1000 GAL	1/18/04	5.00	5.00
84	1	1000 GAL	1/18/04	5.00	5.00
85	1	1000 GAL	1/18/04	5.00	5.00
86	1	1000 GAL	1/18/04	5.00	5.00
87	1	1000 GAL	1/18/04	5.00	5.00
88	1	1000 GAL	1/18/04	5.00	5.00
89	1	1000 GAL	1/18/04	5.00	5.00
90	1	1000 GAL	1/18/04	5.00	5.00
91	1	1000 GAL	1/18/04	5.00	5.00
92	1	1000 GAL	1/18/04	5.00	5.00
93	1	1000 GAL	1/18/04	5.00	5.00
94	1	1000 GAL	1/18/04	5.00	5.00
95	1	1000 GAL	1/18/04	5.00	5.00
96	1	1000 GAL	1/18/04	5.00	5.00
97	1	1000 GAL	1/18/04	5.00	5.00
98	1	1000 GAL	1/18/04	5.00	5.00
99	1	1000 GAL	1/18/04	5.00	5.00
100	1	1000 GAL	1/18/04	5.00	5.00

SK5-6297-1D

UNITED STATES DEPARTMENT OF ENERGY
F. I. DU PONT DE NEMOURS & CO., INC.
SAVANNAH RIVER PLANT

[illegible]

MINI-MELTER	REPAIR MODIFICATIONS	REPAIR PARTS
100	100	100
101	101	101
102	102	102
103	103	103
104	104	104
105	105	105
106	106	106
107	107	107
108	108	108
109	109	109
110	110	110
111	111	111
112	112	112
113	113	113
114	114	114
115	115	115
116	116	116
117	117	117
118	118	118
119	119	119
120	120	120
121	121	121
122	122	122
123	123	123
124	124	124
125	125	125
126	126	126
127	127	127
128	128	128
129	129	129
130	130	130
131	131	131
132	132	132
133	133	133
134	134	134
135	135	135
136	136	136
137	137	137
138	138	138
139	139	139
140	140	140
141	141	141
142	142	142
143	143	143
144	144	144
145	145	145
146	146	146
147	147	147
148	148	148
149	149	149
150	150	150
151	151	151
152	152	152
153	153	153
154	154	154
155	155	155
156	156	156
157	157	157
158	158	158
159	159	159
160	160	160
161	161	161
162	162	162
163	163	163
164	164	164
165	165	165
166	166	166
167	167	167
168	168	168
169	169	169
170	170	170
171	171	171
172	172	172
173	173	173
174	174	174
175	175	175
176	176	176
177	177	177
178	178	178
179	179	179
180	180	180
181	181	181
182	182	182
183	183	183
184	184	184
185	185	185
186	186	186
187	187	187
188	188	188
189	189	189
190	190	190
191	191	191
192	192	192
193	193	193
194	194	194
195	195	195
196	196	196
197	197	197
198	198	198
199	199	199
200	200	200

[illegible]

LATEST REVISION



Westinghouse
Savannah River Company

P.O. Box 616
Aiken, SC 29802

CC: W. F. Perrin, DOE-SR (1)
File(WSRC-RP-89-61)
BSF-ISG-89-0015


May 4, 1989

Ms. W. F. Perrin, Technical Information Officer
U. S. Department of Energy
Savannah River Operations Office
Aiken, SC 29801

Dear Ms. Perrin:

REQUEST FOR APPROVAL TO RELEASE SCIENTIFIC/TECHNICAL INFORMATION

The attached document(s) is (are) submitted for approval for external release. Please complete Part II of this letter and return the letter to the undersigned, by: 05/19/89. Patent clearance is requested and received via direct communication between DOE Patent Counsel and AED Patent Reviewer. The document has ~~not~~ been reviewed for classification and UCNI. The document is ~~classified~~/unclassified and ~~contains no~~/may contain UCNI. (Strike words that do not apply.)



O. J. Banick Classification Officer

I. DETAILS OF REQUEST FOR RELEASE

WSRC-RP-89-61, "BUILDING 774A MINI-MELTER RESTORATION," By D. L. Mensink.

A paper being sent to OSTI for distribution to the general public.

Technical questions pertaining to the contents of the document should be addressed to the author(s) or

C. W. Smith, Manager
Laboratory Service
Savannah River Site

Questions concerning processing of this document should be addressed to the AED Classification Officer & Patent Reviewer at Extension 5-2606.

II. DOE-SR ACTION

DATE RECEIVED BY TIO 5-4-89

☒ Approved as written
☐ Remarks

☐ Not approved as written, ☐ revise and resubmit to DOE,
☐ Approved upon completion of changes marked on document



W. F. Perrin, Technical Information Officer, DOE-SR

Date 5-1-89

DOE AND MAJOR CONTRACTOR RECOMMENDATIONS FOR
ANNOUNCEMENT AND DISTRIBUTION OF DOCUMENTS

1. DOE Report No. WSRC-RP-89-61	2. DOE Contract No. DE-AC09-88SR18305	3. DOE B and R code(s)	4. OSTI UC or C Category No. UC-706
------------------------------------	--	------------------------	--

5. Title
"BUILDING 774A MINI MELTER RESTORATION, BY DL MENSINK

6. Type of Document ("x" one)

- a. Scientific and technical report: ☐ monthly ☐ quarterly ☐ annual ☐ final ☐ topical ☐ other
- b. Conference paper: Name of conference (no abbreviations) _____

Location (city/st/ctry) _____

Date (mo/day/yr) _____

Sponsor _____

Contents: ☐ proceedings ☐ viewgraphs ☐ paper ☐ poster sessions

c. Computer Media:

Document is accompanied by ☐ magnetic tape(s) _____☐ diskette(s) _____☐ other (specify) _____

d. Other (e.g., journal article, manuscript, manual, etc.) (specify) _____

7. Copies Transmitted to OSTI ("x" one or more)

- ☐ a. Copies transmitted for unclassified distribution. ☐ d. Ten copies transmitted for OSTI processing and NTIS sales.
- ☐ b. Copies transmitted for special distribution. ☐ e. Copies transmitted for classified distribution as defined in M-3679.
- ☒ c. Two reproducible copies transmitted. ☐ f. One copy transmitted for OSTI classified processing.

8. Document contains information pertaining to any of the following:

- ☐ Yes ("x" one or more) ☒ No (if no, unlimited distribution may be made within the U.S. In addition, copies may be made available to Foreign requestors through exchange agreements or NTIS sales.)
- ☐ a. Classified
(Announce to addresses in M-3679)
- ☐ b. Official Use Only (OUO)
- ☐ c. Export Control/ITAR/EAR
- ☐ d. Proprietary Information
- ☐ e. Small Business Innovation Research (SBIR)
- ☐ f. Unclassified Controlled Nuclear Information (UCNI)
- ☐ g. Patent Sensitivity
- ☐ h. Translations of copyrighted material
(Boxes b-h will be announced to Government agencies and their contractors)
- ☐ i. Other (explain) _____
(This designation must be in accordance with written DOE Program Office guidance)

Upon demand, OSTI will make distribution of these documents in accordance with existing laws, regulations, and/or written program office guidance.

9. Patent and Copyrighted Information

- a. ("x" one) ☐ 1. DOE patent clearance has been granted by responsible DOE patent group.
- ☐ 2. Document has been sent to responsible DOE patent group for clearance.
- ☒ 3. Patent clearance not required.
- b. Does this material contain copyrighted information? ☒ No ☐ Yes
- If yes, has release been obtained for DOE reproduction? ☐ No ☐ Yes
- (attach release)

10. Additional information, remarks, and special handling instructions. (Do not identify Sigma categories for Nuclear Weapon Data reports, and do not provide additional instructions which are inconsistent with Item 8 above.) (Continue on separate sheet, if necessary)

11. Submitted by (Name and Position) (Please print or type)

J. A. DUSCHINSKI, TECHNICAL INFORMATION MANAGER

Phone

FTS 237-3992

(Organization)

Signature

Date

ISD

6-12-89

**SAVANNAH RIVER
DOCUMENT APPROVAL SHEET**
(See SRP Procedures Manual Item 101)

Document Number WSRC-RP-89-61
UC or C Number _____

1. DESCRIPTION OF DOCUMENT (to be completed by author)

TITLE BUILDING 774A MINI-MELTER RESTORATION
AUTHOR(S) D. L. MENSINK PHONE NO. 53367
TYPE: ☒ INTERNAL DOCUMENT ☐ EXTERNAL DOCUMENT
☐ DP Report
☐ Paper (see below)
☐ Other _____

Additional Information for External Papers

PAPER FOR: Presentation Only _____ Publication Only _____ Both _____
MEETING NAME _____
CITY _____ DATES _____
CHAIRMAN & ADDRESS _____
JOURNAL NAME _____
DEADLINES FOR PUBLICATION: Abstract _____ No. of Copies _____
Paper _____ No. of Copies _____

I understand that for the information in this paper for external distribution:
A. Approvals by both Du Pont and DOE-SR managements are required.
B. Distribution verbally, or by publication, must be in accordance with policies set forth in DOE-SR orders.
C. Content of the external distribution must be limited to that actually approved by DOE-SR.

AUTHOR'S SIGNATURE _____

2. APPROVAL BY AUTHOR'S ORGANIZATION (required for all technical documents)

SRP/SRL ORGANIZATION LABORATORY SERVICES
DERIVATIVE CLASSIFIER R. M. WALLACE
Classification U Topic GLASS MELTERS
DISTRIBUTION _____ Limit to List Attached. Reason: _____
_____ Limit to SRP & SRL. Reason: _____
_____ Limit to DOE-SR & Du Pont Contractual Family. Reason: _____
_____ Site-Specific Procedure, Data Sheet, TA, etc.
☒ Unlimited To General Public

APPROVED BY RESEARCH MANAGER/SUPERINTENDENT [Signature] DATE 4/20/89

3. CLASSIFICATION & PATENT INFORMATION (to be completed by Patent & Classification Reviewer)

CLASSIFICATION (circle one for each)		CLASSIFICATION GUIDE TOPICS	PATENT CONSIDERATIONS
Overall	S C UCN I U	_____	Possible Novel Features _____
Abstract	S C UCN I U	_____	_____
Title	S C UCN I U	_____	Closest Prior Art _____
Cover Letter	S C UCN I U	_____	_____

APPROVED BY AED PATENT & CLASSIFICATION OFFICER _____ DATE _____

4. PUBLICATIONS DIVISION PROCESSING

DATE RECEIVED _____ PUBLICATIONS SUPERVISOR _____
EDITOR _____ DATE ASSIGNED _____
DATE COPIES SUBMITTED FOR RELEASE _____
DOE-SR RELEASE DATES: Patent Branch _____ Tech. Info. Office _____
DATE COMPLETED _____ DATE SUBMITTED TO OSTI _____

SAVANNAH RIVER
DOCUMENT APPROVAL SHEET
(See SRP Procedures Manual Item 101)Document Number WSRC-RP-89-61
UC or C Number UC-706

1. DESCRIPTION OF DOCUMENT (to be completed by author)

TITLE BUILDING 774A MINI-MELTER RESTORATIONAUTHOR(S) D. L. MENSINKPHONE NO. 53367TYPE: ☒ INTERNAL DOCUMENT☐ EXTERNAL DOCUMENT☐ DP Report☐ Paper (see below)☐ Other

Additional Information for External Papers

PAPER FOR: Presentation Only _____ Publication Only _____ Both _____

MEETING NAME _____

CITY _____ DATES _____

CHAIRMAN & ADDRESS _____

JOURNAL NAME _____

DEADLINES FOR PUBLICATION: Abstract _____ No. of Copies _____

Paper _____ No. of Copies _____

I understand that for the information in this paper for external distribution:

A. Approvals by both Du Pont and DOE-SR managements are required.

B. Distribution verbally, or by publication, must be in accordance with policies set forth in DOE-SR orders.

C. Content of the external distribution must be limited to that actually approved by DOE-SR.

AUTHOR'S SIGNATURE _____

2. APPROVAL BY AUTHOR'S ORGANIZATION (required for all technical documents)

SRP/SRL ORGANIZATION LABORATORY SERVICESDERIVATIVE CLASSIFIER R. M. WALLACEClassification U Topic GLASS MELTERS

DISTRIBUTION

_____ Limit to List Attached. Reason: _____

_____ Limit to SRP & SRL. Reason: _____

_____ Limit to DOE-SR & Du Pont Contractual Family. Reason: _____

_____ Site-Specific Procedure, Data Sheet, TA, etc.

_____ ☒ Unlimited To General PublicAPPROVED BY
RESEARCH MANAGER/SUPERINTENDENTDATE 4/20/89

3. CLASSIFICATION & PATENT INFORMATION (to be completed by Patent & Classification Reviewer)

CLASSIFICATION (circle one for each)

Overall S C UCNI UAbstract S C UCNI UTitle S C UCNI UCover Letter S C UCNI U

CLASSIFICATION GUIDE TOPICS

CG-DAR-1Type 1.1

PATENT CONSIDERATIONS

Possible Novel Features NA

Closest Prior Art _____

APPROVED BY AED PATENT
& CLASSIFICATION OFFICERDATE 6/13/89

4. PUBLICATIONS DIVISION PROCESSING

DATE RECEIVED _____ PUBLICATIONS SUPERVISOR _____

EDITOR _____ DATE ASSIGNED _____

DATE COPIES SUBMITTED FOR RELEASE _____

DOE-SR RELEASE DATES: Patent Branch _____ Tech. Info. Office 5/11/89DATE COMPLETED _____ DATE SUBMITTED TO OSTI 6/12/89